

**RECEIVED  
CENTRAL FAX CENTER**

**NOV 15 2007**

Appl. No. 10/771,543

Amdt. Dated November 15, 2007

Notice of Non-Compliant Amendment of November 9, 2007

**Amendments to the Specification:**

Please replace Paragraph [0008] with the following amended paragraph:

[0008] As the door travels along the lower and upper tracks, the top wheel guide wheels or rollers rotate against the inside parallel vertical edges of the E track and maintain a door positioned centrally within the track cavity. However, if the door is adjusted out of vertical, for example, to align the door with a non-vertical side frame or door jam, the wheel no longer runs vertically against the track wall and will cause the door to shake or vibrate as the wheel attempts to correct the misalignment. The door becomes difficult to move and the vibration causes undesirable noises. Furthermore, it is possible that the door may dislodge from the tracks.

The term "spheroidal surfaces" as used herein refers to spherical and elliptical surfaces.